

*Operator Manual*

*2-Phase Stepping Motor Drive*

*smde 285*



Revision: 47/2010

## Product features

For all 2-phase stepping motors, primarily up to 90th motor size

8-wire technology, windings switched parallel or in series

Powerful drive: bipolar chopper, low noise and losses

Only one power supply necessary

Motor current adjustment with HEX-switch

Steps/revolution:

standard: 200, 400, 800, 1600, 500, 1000  
 optional: 400, 500, 1000, 2000

Optimized torque ripple between steps

Step frequency up to 100 kHz

Switchable automatic current reduction

LED-indicators for supply voltage, over current, over temperature, over voltage(ballast), and zero phase

Automatic fan control (optional)

Protected against over temperature, excessively high motor current and power supply voltage surges (integrated active ballast circuit)

Inputs: PULSE, DIRECTION, GATE, OFF, RESET, FAST

Outputs: READY, ZERO-position(Reference point)

All connections via 32pol. VG-socket


European format (100x160x40)mm for 19" technology

## Variants/Order-key


smde 285-x0 80V, 5A  
 smde 285-x1 80V,10A  
 smde 285-x2 130V, 5A  
 smde 285-x3 130V,10A

x: 0: heat sink right  
 1: heat sink left  
 2: cassette

## Placement of the operating elements



## Wiring diagram



## Signal description

### PULS:

A step is executed with each positive signal edge. The power drive exclusively reacts on signal edges. In case of an active current reduction (jumper „current reduction“ inserted) and pulse pauses greater than approx. 100ms, the motor current is reduced to approx. 60% of the set value.

**The current reduction is not active if the pulse signal stays on active.**

### DIR: (Direction)

The direction signal defines the sense of motor rotation. The logic assignment can be inverted by swapping the wires of one motor phase.

### GATE:

The power drive ignore all input pulses if the input GATE is activated. With this function it is possible to operate multiple power drives from one pulse source.

**only active if jumper „Gate enable“ inserted**

### OFF:

When active, the motor current is switched to zero. The motor shaft can now easily be rotated manually.

### READY:


This output is switched when the drive is functional. The following faults switch the output to high impedance: low voltage, over current/temperature. This condition is hold until „RESET-Signal“ is active or the power drive is switched off and on again. The power drive senses READY approx. 200ms after power supply is stable.

### RESET:

Change from error condition to operating condition. Independent of the current motor position, the motor switches to ZERO position.

**While the RESET signal is active, the motor current is switched to zero and the motor is without torque.**

**ZEROPHASE: (Reference point)**



ZERO phase or ZERO position can be used as an exact reference point. Following is a procedure to handle with ZERO points.

First move carefully to the limit switch, reverse the direction and move until ZERO phase is active. Be sure, the ZERO phase don't coincides with the limit switch hysteresis and perhaps adjust the limit switch position.

Depending on the pulses/revolution the ZERO phase becomes active after n pulses under the condition the direction doesn't change

steps/rev.:	ZEROPHASE after n pulses
200	4
400	8
800	16
1600	32
500	10
1000	20

**output active only with jumper „ZERO phase inserted“**

**FAST:**

Activating of this input switches to the halve resolution. So the result is the double motor speed.


! It acts only at the 1600, 1000 and 400 steps/revolution.  
! Switching only at even positions 2,4,6,...

**Motor connections:**

By swapping the wiring connection of one motor phase, e.g. phase A, the motor sense of rotation can be inverted to the logic assignment of the direction signal.

Under no circumstances motor wires must be disconnected during operation. Induction voltages can destroy the power drive. For this reason assure proper contact of the motor wires at the VG socket.

**Interface:**



Optional, the signals can be driven with high or low active levels. There for set the jumper (near VG-socket) to the appropriate position.

The jumper must be inserted in any case

### Steps per revolution

Select the steps/revolution with the DIP-switch.

**! Only when power drive is off**

Using a standard hybrid stepper motor with 50 magnetic poles result in following steps/revolution:

200, 400, 800, 1600,	500, 1000	oder
400,	500, 1000, 2000	optional

### Performance of rotation smoothing:

☹ less than 400 ☺ more than 400

### Behavior of resonance

The resonances can be reduced by increasing the steps/revolution. Following table will show the effect under the condition the resonance at full step will be 100%

steps/rev.:	behavior of resonance
200	100%
400	29%
800	8%

### Motor current setting:

The motor current is set with the HEX switch. In the picture „placement of the operator elements“ on side 2 you can see the motor current according to the position of the HEX switch. The value represents the amplitude of the sinusoidal phase current. The total motor current is the sum  $I_{\text{motor}} = \sqrt{(I_a^2 \sin^2() + I_b^2 \cos^2())}$ .

In general only as much current should be set as actually is required for the application. Too high motor currents results in unnecessary losses in motor and drive.

At higher pulse rates the motor current reduces because of the motor inductance. (see diagrams from manufactures)

### Automatic current reduction

In operating modes with pauses between movements it is useful to activate the current reduction. The motor current is reduced to approx. 60% of the set motor current. The losses in motor and drive are reduced as could be seen in following table:

current reduction	0%	auf 60%	
losses	100%		36%
motor torque	100%		60%

**! Current reduction reduces holding torque. Assure the resulting holding torque is acceptable for your application.**

The current reduction is activated, if the pulse input is inactive for more then approx. 100ms.

The current reduction can be blocked if the pulse input remains in a static active level.

With the next pulse, the current reduction is disabled immediately. The time to full motor current depends on motor type, motor voltage and pulse width(if < 15ys)


**the current reduction must be activated at motor currents over 7,5A**

### Temperature monitoring

The fan automatic (optional) is switched on if the heat sink temperature exceeds approx. 60°C. This should be interpreted as an over temperature warning. The condition is indicated with the LED „over temp.“. The power drive is disabled, if the heat sink temperature exceeds 70° Celsius.

Motor currents grater than 5A makes an additional cooling necessary.

## Reference potential



To reduce fault influences it is highly recommended to have separated power lines for each power drive, especially for the power ground, which acts also as the signal ground.

### Power supply

It must be guaranteed that the power supply have an capacitor of at least 6800yF. An active internal ballast circuit eliminates short over voltages caused by generator operation occurring during fast deceleration. This condition is indicated with the over voltage LED that only be lit for a short period of time during this condition.


Too high motor voltages may damage the power drive.

Never connect live supply voltage wires to the terminals, because the sudden charge current of the internal electrolytic capacitors can destroy the internal fuses

**! Check for correct polarity**

## Timing

! Pulse slope:	max	2 $\mu$ s
! Pulse width:	min	5 $\mu$ s





prt:	> 5 $\mu$ s	gate active after pulse/direction
tpr:	> 10ms	pulse/direction active after gate
pr:	> 5 $\mu$ s	pulse before direction
rp:	> 5 $\mu$ s	pulse after direction
pa:	< 150ms	I-reduction active after pulse
ap:	< 0,5ms	I-reduction disable after pulse
bpo:	< 1s	ready after power-on
eon:	< 100ms	ready after reset



## Dimensions

**! Note: power drives with extruded heat sinks <42mm (standard)**



## Technical specifications:

<b>Power drive supply:</b>	<b>80V</b>	<b>130V</b>
Absolute max. voltage:	85V	135V
Minimum voltage:	24V	65V
recommended voltage Un:	72V	120V
Voltage ripple:		< 2,0Vss
Input peak current at power on:		< 4,0A
Fusing:		5,0Amt
Power supply charge capacitor:		>6800yF
Power supply cable cross section:		0,75mm <sup>2</sup>
Distance to power supply capacitor		<0,3m

### Motor connection:

Cable cross section:	<4A	>0,75mm <sup>2</sup>
	>4A	>1,00mm <sup>2</sup>
Cable length:		<10m

### Signal input interface:

#### Pulse, direction, gate, off, reset

Input type:		RC, HC-MOS
Input voltage	low:	<0,8V
	high	4,0..26,0V
	nominal	5V
Input resistance		ca.5kOhm

#### Fast:

Input type:	low active	10k an 5V
Input voltage:	maximum	0,2V

### Signal output interface:

#### Ready, zero phase

Output type:	Transistor
switching voltage:	<30V
Inner resistance:	<15 Ohm
switching current:	< 50 mA
Load:	only ohmic

### Temperature monitoring:

Warning (fan on):	->ca. 60°
Switch off:	> ca. 70 °

### Current reduction, active at frequencies lower than

Pulse width:	5ys	10ys	50ys	100ys
Current red.:	50Hz	30Hz	20Hz	15Hz

### Ambient conditions:

Temperature:	40° max
UL94V-1 all Components	
IP00	

## Trouble shooting:

### Motor has no holding torque

- The motor voltage is below the minimum value
- Signal inputs "reset" or "off" are active
- The over temperature monitoring is still active
- A non-valid step resolution is selected

### Motor has holding torque, but doesn't execute steps

- The "GATE" input is active
- The pulse level is too low (24V interface)

### "TEMP"-LED is on immediately after power on

- The heat sink couldn't cool down sufficiently

### "Over curr."-LED is on immediately after power on

- The power drive is damaged
- The motor winding has a short cut

### Sudden "crackling" noises in the motor

- Motor is operated at the minimum voltage limit
- The motor connection is bad

### The motor doesn't reach the set speed but starts

- The motor voltage is too low for the required speed
- The motor current was set too low
- The acceleration ramp was set too high
- Motor wires are too long or too small cross section
- Power supply is not powerful enough

### The motor "loses" steps and drifts

- The amplitudes of the control signals are too low
- Signal cable noise is too high (shielded cables?)
- The wiring concept is not optimal (system ground)
- The mechanical shaft coupling has play

### Motor vibrates at pulse frequency and doesn't start

- Start/Stop-frequency too high
- Motor windings are connected wrong or broken cable
- The motor current is set too low

### The automatic current reduction doesn't work

- The pulse input remains active after the last
- The current reduction is not enabled

### The over voltage LED is often/permanently lit

- The supply voltage is too high

### The motor is hot

Up to 85 ° Celsius should be no problem

### Step angle too different

- Motor inductance is too high
- Motor current too less

### Signal gate, zero phase without reaction

- the jumpers are not inserted