

Operator Manual

3-Phase Stepping Motor Drive

smde 385



Revision: 47/2010 changes without notice

Product features

For all 3-phase stepping motors, primarily up to 90th motor size

Windings in star or triangle mode

Powerful drive: chopper, low noise and losses

Only one power supply necessary

Motor current adjustment with HEX-switch

Steps/revolution:
 standard: 500, 1000, 2000
 optional: 200, 400, 800, 1600, 500, 1000

Optimized torque ripple between steps

Step frequency up to 100 kHz

Switchable automatic current reduction

LED-indicators for supply voltage, over current, over temperature, over voltage(ballast), and zero phase

Automatic fan control (optional)

Protected against over temperature, excessively high motor current and power supply voltage surges (integrated active ballast circuit)

Inputs: PULSE, DIRECTION, GATE, OFF/RESET, FAST(optional)

Outputs: READY, ZERO-position(optional)

All connections via 32pol. VG-socket


European format (100x160x40)mm for 19" technology

Variants/Order-key


smde 385-x0 80V, 5A
 smde 385-x1 80V,10A
 smde 385-x2 130V, 5A
 smde 385-x3 130V,10A

x 0: 24V Signal 1: 5Volt Signal

Placement of the operating elements



Wiring diagram



Signal description

PULS:

A step is executed with each positive signal edge. The power drive exclusively reacts on signal edges. In case of an active current reduction (jumper „current reduction“ inserted) and pulse pauses greater than approx. 100ms, the motor current is reduced to approx. 60% of the set value.

The current reduction is not active if the pulse signal stays on active.

DIR: (Direction)

The direction signal defines the sense of motor rotation. The logic assignment can be inverted by swapping the wires of one motor phase.

GATE:

The power drive ignore all input pulses if the input GATE is activated. With this function it is possible to operate multiple power drives from one pulse source.

OFF/RESET:

When active, the motor current is switched to zero. The motor shaft can now easily be rotated manually. The stepping counter is not modified.

OFF/RESET:


Change from error condition to operating condition. In error condition, the motor has now torque. With RESET not active, the power drive is initialised and the stepping counter has zero position.

While the RESET signal is active, the motor current is switched to zero and the motor is without torque.

READY

This output is switched when the drive is functional. The following faults switch the output to high impedance: low voltage, over current/temperature. This condition is hold until „RESET-Signal“ is active or the power drive is switched off and on again. The power drive senses READY approx. 200ms after power supply is stable.

ZEROPHASE: (Reference point)



ZERO phase or ZERO position can be used as an exact reference point. Following is a procedure to handle with ZERO points.

First move carefully to the limit switch, reverse the direction and move until ZERO phase is active. Be sure, the ZERO phase don't coincides with the limit switch hysteresis and perhaps adjust the limit switch position.

Depending on the pulses/revolution the ZERO phase becomes active after n pulses under the condition the direction doesn't change

steps/rev.:	ZEROPHASE after n pulses
200	4
400	8
800	16
1600	32
500	10
1000	20

output active only with jumper „ZERO phase inserted“

FAST:

Activating of this input switches to the halve resolution. So the result is the double motor speed.


! It acts only at the 1600, 1000 and 400 steps/revolution.
! Switching only at even positions 2,4,6,...

Motor connections:

By exchanging two phases, e.g. phase U and V, the motor sense of rotation can be inverted to the logic assignment of the direction signal.

Under no circumstances motor wires must be disconnected during operation. Induction voltages can destroy the power drive. For this reason assure proper contact of the motor wires at the VG socket.

Interface:



Both signals of the opto coupler, plus and minus are available on the connector. So its easily possible to operate the interface with high or low level oriented signals.

! Attention:
 Never supply a 24Volt signal on a 5Volt configured interface (resistor net inserted), because of damaging the opto coupler

Steps per revolution

Select the steps/revolution with the DIP-switch.

! Only when power drive is off

Using a standard hybrid stepper motor with 50 magnetic poles result in following steps/revolution:

500, 1000, 2000	or optional
200, 400, 800, 1600,	500, 1000

Performance of rotation smoothing:

☹ less than 400 ☺ more than 400

Behavior of resonance

The resonances can be reduced by increasing the steps/revolution. Following table will show the effect under the condition the resonance at full step will be 100%

steps/rev.:	behavior of resonance
200	100%
400	29%
800	8%

Motor current setting:

The motor current is set with the HEX switch. In the picture „placement of the operator elements“ on side 2 you can see the motor current according to the position of the HEX switch. The value represents the amplitude of the sinusoidal phase current. The total motor current is the sum of the three 120 degree shifted phases.

In general only as much current should be set as actually is required for the application. Too high motor currents results in unnecessary losses in motor and drive.

At higher pulse rates the motor current reduces because of the motor inductance. (see diagrams from manufactures)

Automatic current reduction

In operating modes with pauses between movements it is useful to activate the current reduction. The motor current is reduced to approx. 60% of the set motor current. The losses in motor and drive are reduced as could be seen in following table:

current reduction	0%	auf 60%
losses	100%	36%
motor torque	100%	60%

! Current reduction reduces holding torque. Assure the resulting holding torque is acceptable for your application.

The current reduction is activated, if the pulse input is inactive for more then approx. 100ms.

The current reduction can be blocked if the pulse input remains in a static active level.

With the next pulse, the current reduction is disabled immediately. The time to full motor current depends on motor type, motor voltage and pulse width(if < 15µs)


the current reduction must be activated at motor currents over 7,5A

Temperature monitoring

The fan automatic (optional) is switched on if the heat sink temperature exceeds approx. 60°C. This should be interpreted as an over temperature warning. The condition is indicated with the LED „over temp.“. The power drive is disabled, if the heat sink temperature exceeds 70° Celsius.

Motor currents grater than 5A makes an additional cooling necessary.

Reference potential



To reduce fault influences it is highly recommended to have separated power lines for each power drive, especially for the power ground, which acts also as the signal ground.

Power supply

It must be guaranteed that the power supply have an capacitor of at least 6800yF. An active internal ballast circuit eliminates short over voltages caused by generator operation occurring during fast deceleration. This condition is indicated with the over voltage LED that only be lit for a short period of time during this condition.


Too high motor voltages may damage the power drive.

Never connect live supply voltage wires to the terminals, because the sudden charge current of the internal electrolytic capacitors can destroy the internal fuses

! Check for correct polarity

Timing



! Pulse slope:	max	2ys
! Pulse width:	min	5ys



prt:	> 5ys	gate active after pulse/direction
tpr:	> 10ms	pulse/direction active after gate
pr:	> 5ys	pulse before direction
rp :	> 5ys	pulse after direction
pa:	<150ms	I-reduction active after pulse
ap:	< 0,5ms	I-reduction disable after pulse
bpo:	< 1s	ready after power-on
eon:	<100ms	ready after reset

Dimensions

! Note: power drives with extruded heat sinks <42mm (standard)



Technical specifications:

Power drive supply:	80V	130V
Absolute max. voltage:	85V	135V
Minimum voltage:	24V	65V
recommended voltage Un:	72V	120V
Voltage ripple:		< 2,0Vss
Input peak current at power on:		< 4,0A
Fusing:		5,0Amt
Power supply charge capacitor:		>6800yF
Power supply cable cross section:		0,75mm ²
Distance to power supply capacitor		<0,3m

Motor connection:

Cable cross section:	<4A	>0,75mm ²
	>4A	>1,00mm ²
Cable length:		<10m

Signal input interface:

5V (24V)

Pulse, direction, gate, off, reset

Input type:		opto coupler
Input voltage	low:	<1V(2V)
	high	>3,5V(15V)
	nominal	5V(24V)
Input resistance		6V(28V)

Signal output interface:

Ready:

Output type:	Relai, 36V, 100mA
Load:	only ohmic

Zerophase:

Output type:	Opto coupler
	<30V, Ri<15 Ohm, <50 mA
	load ohmic

Temperature monitoring:

Warning:	->ca. 60°
Switch off:	> ca. 70 °

Current reduction, active at frequencies lower than

Pulse width:	5ys	10ys	50ys	100ys
Current red.:	50Hz	30Hz	20Hz	15Hz

Ambient conditions:

Temperature:	40° max
UL94V-1 all Components	
IP00	

Trouble shooting:

Motor has no holding torque

- The motor voltage is below the minimum value
- Signal inputs "reset" or "off" are active
- The over temperature monitoring is still active
- A non-valid step resolution is selected

Motor has holding torque, but doesn't execute steps

- The "GATE" input is active
- The pulse level is too low (24V interface)

"TEMP"-LED is on immediately after power on

- The heat sink couldn't cool down sufficiently

"Over curr."-LED is on immediately after power on

- The power drive is damaged
- The motor winding has a short cut

Sudden "crackling" noises in the motor

- Motor is operated at the minimum voltage limit
- The motor connection is bad

The motor doesn't reach the set speed but starts

- The motor voltage is too low for the required speed
- The motor current was set too low
- The acceleration ramp was set too high
- Motor wires are too long or too small cross section
- Power supply is not powerful enough

The motor "loses" steps and drifts

- The amplitudes of the control signals are too low
- Signal cable noise is too high (shielded cables?)
- The wiring concept is not optimal (system ground)
- The mechanical shaft coupling has play

Motor vibrates at pulse frequency and doesn't start

- Start/Stop-frequency too high
- Motor windings are connected wrong or broken cable
- The motor current is set too low

The automatic current reduction doesn't work

- The pulse input remains active after the last
- The current reduction is not enabled

The over voltage LED is often/permanently lit

- The supply voltage is too high

The motor is hot

Up to 85 ° Celsius should be no problem

Step angle too different

- Motor inductance is too high
- Motor current too less

Signal gate, zero phase without reaction

- the jumpers are not inserted